



Kryton Buildmat Co. Pvt. Ltd. 136-137 Centrum Plaza, Golf Course Road, Sector 53, Gurugram, Haryana 122002

Telefax: +91-124-4381140 / 41 Email: custcare@kryton.in Web: www.kryton.in





NEGATIVE SIDE LEAK REPAIR

POSITIVE SIDE LEAK REPAIR

## **CRACK LEAK REPAIR**

## MANUFACTURER'S NOTES:

CHISEL TO CREATE A CHASE ALONG THE ENTIRE LENGTH OF THE LEAKING CRACK OR JOINT TO THE REQUIRED 25 MM X 25 MM (1" X 1.")

- 1. APPLY KRYSTOL PLUG TO PREPARED CHASE TO STOP FLOWING WATER.
- 2. TIGHTLY PACK REMAINING CHASE WITH KRYSTOL WATERSTOP GROUT
- 3. POSITIVE SIDE WATERPROOF ENTIRE WALL OR SLAB WITH KRYSTOL T1.
- 4. NEGATIVE SIDE ADDITIONAL COAT AFTER 3 TO 4 HOURS WITH KRYSTOL T2.

## NOTES:

- 1. INSTALLATION TO BE COMPLETED IN ACCORDANCE WITH MANUFACTURER'S SPECIFICATIONS.
- 2. DO NOT SCALE DRAWING.
- 3. THIS DRAWING IS INTENDED FOR USE BY ARCHITECTS, ENGINEERS, CONTRACTORS, CONSULTANTS AND DESIGN PROFESSIONALS FOR PLANNING PURPOSES ONLY. THIS DRAWING MAY NOT BE USED FOR CONSTRUCTION.
- 4. ALL INFORMATION CONTAINED HEREIN WAS CURRENT AT THE TIME OF DEVELOPMENT BUT MUST BE REVIEWED AND APPROVED BY THE PRODUCT MANUFACTURER TO BE CONSIDERED ACCURATE.



LR 5104-033 REVISION DATE 2024